


Project Name: FEATHERSOUND POND BANK STABILIZATION

SCOPE:

Gator Dredging was contacted by Feather Sound Executive Center Association for a failing pond that had bank erosion. The staff of Gator Dredging was able to meet on site with the president of the association to asses and propose a strategy to restore and stabilize 130ft of the pond bank in order to protect the slopes from further erosion.

Necessary equipment and material was provided by Gator Dredging to successfully stabilize the eroding bank. Specialized mirafied geo synthetic fabric was used to line the bank of the pond in preparation for riprap to be installed. Crushed concrete was used for the riprap installation which completed the stabilization of the pond banks while creating an aesthetically pleasing setting for the Association.

Project Location:	Clearwater, Florida
Name of Owner:	Feather Sound Executive Centers Association
Dates of Construction:	April - May 2010



Proposed Bank Section View



Before - Eroding Pond Bank



After - Rip Rap Installation